


**City of Chicago
Department of Environment**



NARRATIVE

**Date: 3-22-99
Site: 4751 S. Morgan
Site Code:**

**Time: 12:05pm - 1:05pm
Inspector: T. Sheahan
County: Cook/Chicago**

I arrived at the above location in response to a complaint regarding a diesel fuel spill. Upon arrival, I met the owner of Wheeler Trailer, Mr. Randy Wheeler. He allowed me to inspect the site without an escort because he was going to a meeting. Mr. Wheeler stated that he did not know of any spill at the site.

I proceeded to inspect the site when I came upon a large pool of oil on the ground behind the repair/work shop. The pool of oil was approximately 100ft. long by 6ft. across. I could not find a source for the oil spill at the time of inspection. Mr. Wheeler stated that he did not know where the oil came from because he never goes behind the work shop. He said that the oil may be coming from the landfill.

This spill is located next to an illegal landfill where rubber, plastic, metal, asphalt, concrete, paper and rubbish are buried.


I also observed an area of oil saturated soil next to and under some parked trailers on site. I spoke to Investigator Robertson, who stated that he cited Wheeler Trailer for improper disposal and will return the next day with a representative from Fire Prevention (see Robertson report) to insist on clean up of the oil spill.

SEE ATTACHED PHOTOS AND SKETCH

CITY OF CHICAGO
DEPARTMENT OF ENVIRONMENT
Photographs

Date: 3-21-00
Site: 4700-4800 S. MORGAN
Site Code: _____

Time: 11:00AM-11:55AM
Inspector: T. SHEAHAN
County: COOK-CHICAGO



Roll # _____ Photo # 1 Direction WEST
Comments: ROCKS & CONCRETE ON SIDE OF HILL.



Roll # _____ Photo # 2 Direction WEST
Comments: DEBRIS ON SIDE OF HILL

CITY OF CHICAGO
DEPARTMENT OF ENVIRONMENT
Photographs

Date: 3-21-00
Site: 4700-4800 S. Morgan
Site Code: _____

Time: 11:10AM - 11:55AM
Inspector: T. SHERHAN
County: Cook - CHICAGO



Roll # _____ Photo # 3 Direction WEST
Comments: BURNT OUT CAR AND CONCRETE ON SIDE OF HILL.



Roll # _____ Photo # 4 Direction WEST
Comments: DEBRIS AND GARBAGE ON SIDE OF HILL.